



Houng Lee Kaba Jacob Limited

Suva:
Level 2, Vinnu House,
Victoria Parade, Suva,
GPO Box 12438,
Fiji Islands.
Phone 679 3305 638
Fax 679 3305 231

Auckland:
Unit 3,
25 Dacre Street,
Newton, Auckland,
PO Box 68764 Newton,
Auckland 1165,
New Zealand.
Phone 64 9 377 5622
Fax 64 9 375 2526

CYCLONE WINSTON PRELIMINARY ASSESSMENT SCHOOLS, HEALTH FACILITIES & PUBLIC BUILDINGS


FOR

**THE FIJI INSTITUTION OF ENGINEERS & DEPARTMENT OF
NATIONAL PLANNING (MINISTRY OF FINANCE)**



NAME OF FACILITY:	Ba Sangam Primary School
TYPE:	Primary School & Kindergarten
LOCATION:	Ba
DATE OF ASSESSMENT:	22 March 2016
DATE OF REPORT:	06 April 2016
JOB NO:	16015
HLKJACOB REPORT NO:	19-S
HLKJACOB FACILITY NO:	12
GOVERNMENT FACILITY NO:	025

DISCLAIMER: THIS REPORT HAS BEEN PREPARED FOR THE BENEFIT OF FIJI INSTITUTION OF ENGINEERS & MINISTRY OF FINANCE TO ESTABLISH THE EXTENT OF DAMAGES BASED ON A HIGH LEVEL PRELIMINARY ASSESSMENT. IN NO CIRCUMSTANCES IS THE REPORT TO BE USED FOR SCOPING OR ESTABLISHMENT OF DETAILED COSTS FOR DAMAGES. NO RESPONSIBILITY SHALL BE TAKEN FOR ANY INCORRECT OR INCOMPLETE INFORMATION DUE TO THE SHORT TIME IN CARRYING OUT THE INITIAL ASSESSMENT AS PART OF VOLUNTARY PRO-BONO SERVICE OFFERED BY HLKJACOB. DETAILED ASSESSMENT SHOULD BE CARRIED OUT FOR DETAILED COST AND SCOPE FOR REPAIR AND REINSTATEMENT WORKS.



PHOTOS – BUILDING 1



Photo 1: Overall View of Building 1 Frontage – Classroom & Admin



Photo 2: Overall View of Building 1 Rear /Split Level



Photo 3: Roof view/Damaged downpipe




Photo 4: Showing Damaged door leaf



Photo 5: Showing TypicalAwning Windows / Damaged Gutters



Photo 6: Showing typical water damaged ceiling



PHOTOS – BUILDING 2



Photo 7: Showing Front View of Hall



Photo 8: Showing Side View of Hall



Photo 9: Showing Hall ceiling boards blown off



Photo 10: Showing typical Windows /Blown off gutters



Photo 11: Showing water leak stains



PHOTOS – BUILDING 3



Photo 12: Total destruction of Building 3-Kindergarten




PHOTOS – BUILDING 4: SCHOOL QUARTERS



Photo 13: Showing Overall view of Quarters



Photo 14: Showing newly replaced roof cladding



PHOTOS – GENERAL SITE



Photo 15: Typical Minor damages to Toilet Plumbing



SITE PLAN & OTHER SKETCHES