

CYCLONE WINSTON PRELIMINARY ASSESSMENT SCHOOLS, HEALTH FACILITIES & PUBLIC BUILDINGS


FOR

**THE FIJI INSTITUTION OF ENGINEERS & DEPARTMENT OF
NATIONAL PLANNING (MINISTRY OF FINANCE)**



NAME OF FACILITY:	Ba Sangam College
TYPE:	Secondary School
LOCATION:	Ba
DATE OF ASSESSMENT:	21 March 2016
DATE OF REPORT:	07 April 2016
JOB NO:	16015
HLKJACOB REPORT NO:	40-S
HLKJACOB FACILITY NO:	6
GOVERNMENT FACILITY NO:	7

DISCLAIMER: THIS REPORT HAS BEEN PREPARED FOR THE BENEFIT OF FIJI INSTITUTION OF ENGINEERS & MINISTRY OF FINANCE TO ESTABLISH THE EXTENT OF DAMAGES BASED ON A HIGH LEVEL PRELIMINARY ASSESSMENT. IN NO CIRCUMSTANCES IS THE REPORT TO BE USED FOR SCOPING OR ESTABLISHMENT OF DETAILED COSTS FOR DAMAGES. NO RESPONSIBILITY SHALL BE TAKEN FOR ANY INCORRECT OR INCOMPLETE INFORMATION DUE TO THE SHORT TIME IN CARRYING OUT THE INITIAL ASSESSMENT AS PART OF VOLUNTARY PRO-BONO SERVICE OFFERED BY HLKJACOB. DETAILED ASSESSMENT SHOULD BE CARRIED OUT FOR DETAILED COST AND SCOPE FOR REPAIR AND REINSTATEMENT WORKS.



PHOTOS – BUILDING 1



Photo 1: Front View of Block A




Photo 2: Rear View of Block A



Photo 3: Showing Gutter Damaged/Blown Away



Photo 4: Showing Verandah Ceiling Damaged/ Blown away



PHOTOS – BUILDING 2



Photo 5: Front View of Block C



Photo 6: Rear View of Block C




Photo 7: Side View of Block C



Photo 8: Verandah Ceiling Damaged/ Blown away




Photo 9: Showing Roof View



Photo 10: View of ponding floor



SITE PLAN & OTHER SKETCHES

